

Sanyo

Mistral 1000 / R



Motor Exchange
Rebuild Price Available!
OEM:26091006
P/N:OCM-15



Brush Pair
Soldering Required
OEM:61600
P/N:CB-105



Brush Pair
No Soldering Required
OEM:NA
P/N:CB-105A

Mistral 2000 / R



Motor Exchange
Rebuild Price Available!
Mistral 2000
OEM:66500-816
P/N:OCM-15A



Motor Exchange
Rebuild Price Available!
Mistral 2000R
OEM:66500-816
P/N:OCM-15A-1



Brush Pair
Non-Autostop
OEM:34500-015
P/N:CB-113



Brush Pair
Auto-Stop Brush
OEM:NA
P/N:CB-113A



Lid Screw, Each
OEM:34500-015
P/N:40001



Rotor Bolt
OEM:34500-015
P/N:40002



Fuse Holder
OEM:34500-015
P/N:40005



Lock Microswitch
OEM:34500-015
P/N:40006



Solenoid
OEM:34500-015
P/N:40011



Tension Spring
OEM:78100-087
P/N:40013



Imbalance Switch
OEM:61200-197
P/N:40016



Triac Kit
OEM:61200-262T
P/N:40018



Lid Hinge
OEM:81900-474U
P/N:40037



Tension Spring
OEM:78100-087
P/N:40031



Left Torsion Spring
OEM:78100-112
P/N:40035