## Ozark Biomedical, LLC

Web Site: www.ozarkbiomedical.com 1001 Commerce PL Ph # 800.457.7576 Beebe, AR 72012 Fax # 501.882.2122

|    |    | _           | 1 | _ |
|----|----|-------------|---|---|
| IJ | u  | 0           | t | e |
| ~  | o. | $\mathbf{}$ | • | v |

| Date      | Quote # |  |
|-----------|---------|--|
| 2/23/2024 | 1577    |  |

| Name / Address |  |  |
|----------------|--|--|
|                |  |  |
|                |  |  |
|                |  |  |
|                |  |  |

| Rep | Project |  |
|-----|---------|--|
| DM  |         |  |

| Description   | Qty  |       | Total    |
|---|------|-------|----------|
| Flat rate repair for EBA 20S. ; Rotor/housing not included in flat-rate |      |       | 884.00   |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
|   |      |       |          |
| Please Decontaminate Return Centrifuge Prior To Shipping!               | Tota | <br>I | _        |
|   | IUIa | •     | \$884.00 |